

Hydrophone Spectral Density aligned vs Arrival Time
with 1000 sample window at -125 Hz
H10 Nov 15 2017 14:58:04 Submarine ARA San Juan implosion
-- spectrum alignment bearing 218.003

